



K:\Jobs\090557-San Jacinto\090557-01 - San Jacinto\09055701-RP-092.dwg Fig 3-6



SOURCE: Drawing prepared from USACE. Bathymetry has been compiled from a 2/16/09 and 6/12/10 survey conducted by Hydrographic Consultants, LTD of Bellaire, Texas. Upland contours generated from LiDAR data collected by Merrick & Co., published 11/4/2008.
HORIZONTAL DATUM: Texas South Central NAD 83, US Survey Feet.
VERTICAL DATUM: NAVD 88.
NOTES:
 1. Deep wells are double cased (not depicted) into Upper Beaumont Clay.

ABBREVIATIONS:
 BGS Below Ground Surface
 SJ Borings by MIMC / IPC
 USACE United States Army Corps of Engineers



Dec 03, 2012 11:42am dholmer

Figure 3-6
 General Stratigraphy of the Impoundments North of I-10, Cross Section A-A'
 Remedial Investigation Report
 San Jacinto River Waste Pits Superfund Site