


N:\GIS\Projects\C643_SJWaste_IPC\Production_MXD\sjPre_maintenance_Armored_Cap\Figure4_Dec2015_TEQ_Result_zoom.mxd 2/12/2016 2:11:21 PM



- △ December 2015 Sediment Sample
- ◇ December 2015 Sediment Sample (Split)
- ▲ USEPA Probe Location (December 2015), Rock
- USEPA Probe Location (December 2015), Sediment

Note: J = Estimated Concentration

- October 2015 Bathymetric and Topographic Contours (1-ft interval)
- Toe of Actual Armor Rock Placement
- Toe of Proposed Armor Rock Placement
- Extent of Required Overlap
- Original 1966 Perimeter of the Impoundments North of I-10

Figure 4
Results of Sediment Sampling Conducted on December 23, 2015 in Close Up
TEQ_{DF} (ng/kg dw)
Pre-maintenance Armored Cap
Surface Sediment Sampling Report
San Jacinto River Waste Pits Superfund Site